

International Road Dynamics Inc.

Site Service Sheet

Clear

Date: <u>11/14/2011</u> State: <u>TN</u> Location: <u>Jackson TN, MI 91.6 I-40 West</u>

Job #: ____1378 Site #: _____ LTPP ID: TN-1

Loops

Resistance Resist. to shld Meg Ohm Inductance Condition

Lane -	1	Lane -	2	Lane -	3	Lane -	4
Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail
1.7	1.7	2.4	2.5	1.6	2.0	1.0	1.7
OL	OL	N/A	N/A	N/A	N/A	N/A	N/A
2.3M	4.6M	1.6M	1.6M	3.5M	20.0M	18M	13M
162.0	158.0	148.0	143.0	140.0	136.0	129.0	141.0
ok	ok	ok	ok	ok	ok	ok	ok

Low Meg Ohm readings but all working okay for now

Kistlers

Resist. To shId Capacitance Condition Notes

Lane -	1	Lane -	2	Lane -	3	Lane -	4
OL	OL	OL	OL	OL	OL	OL	OL
22nF	21nf	20.2nF	18nF	15.3nF	17nF	14.6nF	12.3nF
ok	ok	ok	ok	ok	ok	ok	ok

System

A/C Service
Power Supply
Solar Panel
Back-Up
System Input
Modem Power
Phone off hook
Phone on hook

122.VAC
12.0VDC
None
13.VDC
12.0VDC
12.1VDC
ok
ok

Т	em	n	Se	ns	or
_		Г			_

26°C

Technician: <u>Doug Vines</u> Date: <u>#####</u>	<u>###</u>
--	------------

Lane -	4
OL	OL
12.5nF	12nF
ok	ok